TO: Patrick Nejand, Project Manager

Ken Mass, Project Manager

United States Army Corps of Engineers (USACE)

FROM: Shannon Lloyd, Project Manager

Los Alamos Technical Associates, Inc. (LATA)

SUBJECT: February 2015 Inspection Report for the former Cornell Dubilier Electronics (CDE)

Superfund Site, South Plainfield, New Jersey

LATA Project # 11266

Contract # W912DQ-09-D-3003,

Task Order # 0011

DATE: February 19, 2015

### **CURRENT ACTIVITIES**

LATA's technician visited the Cornell Dubilier Electronics (CDE) Superfund Site for the regularly scheduled inspection visit on February 13, 2015 to perform the routine inspection of the facilities.

Work performed during the visit included; picked up trash from the fence line, inspected the catch basin and drainage basin system, inspected the perimeter fence, gates, etc., pulled woody vegetation from accessible areas of the drainage basin, download the data from the basin dataloggers and performed a walking inspection of the asphalt cap areas. Copies of the inspection forms and photo documentation of the site visit are attached to this report. Snow removal and clearing of the sidewalk paralleling Hamilton Boulevard was completed as needed during the month.

Approximately one bag of trash (paper, plastic bottles, etc.) was picked up from around the fence line in various areas. The trash was disposed of in the local technicians office dumpster.

### MANPOWER REPORTING

Date	LATA Labor
February 13, 2015	Approx. 3 hrs.

### **OUTSTANDING ISSUES/RESOLUTIONS**

None

### PLANS FOR NEXT MONTH

Plans for the March 2015 visit includes inspection and general housekeeping activities and downloading the drainage basin level datalogger. A snow removal company has been placed under contract to remove snow from the sidewalk paralleling the Hamilton Boulevard when snowfall totals are greater than two inches. This removal will be made on an as needed basis.

# Site Inspection Forms and Photo Log

Inspection being Co	nducted	X	Monthly				
Quarterly		Annually		_After 1" or Grea	nter Rainfall		
Inspection Date:	2/13/2015	i .		Weather	Sunny, 20s		
Inspectors Name	Sunil Samar	00					
Basin Inspection:					Vos	No	NI/A
Catch Basins (23 Str	uctures)				Yes	No	N/A
1. Are catch basins p	•	g?			Х		
2. Are the catch basi	ins clear of tras	h, sediment and debr	ris?		$\overline{\mathbf{x}}$	一	一
		om all catch basin are				一	$\overline{\mathbf{x}}$
_		deterioration of cato				$\overline{x}$	
If yes, which catch b	_	deterioration of eate	on busins.				ш
(Refer to Record Dra	` '	basin numbers)					
Stormwater Detenti	ion Basin and S	urface Sand Filter:					
5. Does the basin ha	ve pooled or st	anding water?			X		
If yes, describe when		A thin layer of ice w	as observed i	n all 3 detention	basins		
6. What is the water	•	~ 1"					
Approximately how		s the last rainfall?					
How many inches of		h . fl-+2 N d l					
7. Does the bottom	appear relative	ly flat? No sand has w	vasned away?		LX		
8. Are concentrated	flows of runoff	being unexpectedly	directed into	the basin?		X	
If yes, describe when	re						
9. Is there any dama		bed or berms?				Х	
10. Has vegetation b	een removed f	rom the basin areas?					Χ
Woody v	egetation was	removed by pulling/	cutting at gro	ound level.			

Inlet and Outlet Structures:  11. Are the five inlet and outlet structures draining properly?	X		
12. Is there any standing water? If yes, describe where		X	
13. Are the inlets clear of trash, sediment and debris?	Χ		
14. Are the outlets (standpipes, 3" Orifice, secondary outlet and emergency spillway) clear of trash, sediment, and debris?	X		
15. are there any signs of damage or deterioration of inlet/outlet structures?  If yes, describe where		X	
16. Has vegetation been removed from inlet and outlets?			Χ
Additional descriptions of where repairs or maintenance is needed:			
Inspector's Signature Auril Auril Terrardo			

Inspector's Signature

Inspection Date:	2/13/2015	Weather	Sunny, 20s		
Inspectors Name	Sunil Samaroo				
		"Tree Grove" Inspection			
			Yes	No	N/A
1. Is there any tree da	image from storms?			X	
If yes, describe:					
2. Is there an accumu	lation of tree debris?			Χ	
If yes, describe:					
3. Do any trees appea	r infested?				X
If yes, describe:					
4. Do any trees appear	r malnourished?				Χ
If yes, describe:		6 10			
	erly Seasonal Maintenance Pe	rformed?			X
Date of previous mair		anaa Manual)			
•	2 of the Operation & Maintena Il Arborist Inspection performa				
Date of previous inspe	•	eur			<u> </u>
	of the Operation & Maintena	ance Manual)			
(Neier to section 2.5.	of the operation & Mainten	since Maridary			
Additional description	ns of where repairs or mainter	nance is needed:			
Tree buffe	er being maintained "as is" by	direction of USACE and EPA.			
_					
Inspector's Signature	Suril Aur	nardo			

Inspection Date:	2/13/2015	Weather	Sunny, 20s	
Inspectors Name	Sunil Samaroo			
Debris, Trash, Vege Comments	tation and Sediment Removal ar	nd Inspections		
	d trash from perimeter fence.			
	of trash (< 1/2 of bag) disposed	of at URS dumpster.		
	the site remains in good condit	<u> </u>		
General Housekeep	ing			
Comments				
Asphalt	has minor cracking predominant	tly at seems, previously observed.		
Fanaina and Catas				
Fencing and Gates Comments				
GOOD				
-				
Trash and Debris				
Comments				
( See ab	ove )			
-				
Snow Removal				
Comments				
N/A				

Pavement Inspection (Part of Annual Inspection)

Inspector's Signature

	Yes	No	N/A
1. Is there any standing water?			X
If yes, describe where			
2. Are there any signs of cracking?	Χ		
If so, note location and maintenance effort below.			
3. Are there any signs of disintegration?			Χ
If so, note location and maintenance effort below.			
4. Are there any sins of distortion?			Χ
If so, note location and maintenance effort below.			
5. Has all vegetation been removed?	Χ		
If applicable, note location of vegetation below			
6. Has usage of the site increase to a point that warrants a Pavement Condition			Χ
Index (PCI) Survey?			
7. Have any Critical Preventative Maintenance (CPM) Pavement Treatments			Χ
been applied?			
When was date of the last CPM treatment?			
(Refer to Section 2.2.3 of the Operations & Maintenance Manual)			
Additional descriptions of where repairs or maintenance is needed:			
Cracks in asphalt developing in the area of the water tower, previously observe	d.		
Jamestar's Signature Auril Auril Auril			

Basin Drainage Rate Inspection: (completed twice a year after a design rainfall event)				
Date:				
Design Rainfall Event In Requirements: 1.25" of				
Start:				
Stop: Inches of Rainfall:				

### **Inspection Data**

Start inspections 16 hours after design rain event Perform subsequent inspection every 2 hours until height of water drops below the to of the aggregate in the middle basin

Inspection Run #	Target time from Event (hrs)	Actual Time	Water Height (ft)
1	16		
2	18		
3	20		
4	22		
5	24		
6	26		
7	28		
8	30		
9	32		
10	34		

Note approximate time water was drained below top of sand bed and compared to the normal drain time of 21 hrs.

Inspector's Signature

# 02-13-2015 Cornell-Dubilier Electronics

# **Site Inspection photos**

Fence drive by inspection photos















Additional site photos



(Rolling gate along Spicer Avenue was open when getting on-site)



















